



April 27, 1992 Project C34-08.01

Mr. Boramy Ith Douglas Aircraft Company 3855 Lakewood Boulevard Mail Code 74-41 Long Beach, California 90846

Subject: Closure Report for Underground Storage
Tanks 9T, 10T, and 15T through 18T
Douglas Aircraft Company - Torrance Facility (C6)
19503 South Normandie Avenue
Torrance, California 90502 (Contract LS-25833-C)

Dear Mr. Ith:

EMCON Southwest (EMCON) is pleased to report the tank closure and related soil sampling activities for underground storage tanks no. 9T, 10T, and 15T through 18T at the referenced Douglas Aircraft Company (DAC) facility. The closure and sampling activities were performed at the request of DAC in accordance with EMCON's revised workplan dated August 30, 1991.

SUMMARY

The following is a summary of the findings and conclusions of tank closure and soil sampling activities which are discussed in the remainder of this report.

- Excavation and removal of underground storage tanks 9T, 10T, and 15T through 18T were completed during October 11 and 12, 1991.
- Vadose wells 9TW and 10TW (adjacent to tanks 9T and 10T) and a concrete wash slab (near tank 15T) were removed and a surface runoff drain (adjacent to tank 9T) was backfilled during excavation activities.

SCANN""

- A total of 18 soil samples were collected for chemical analysis from beneath the tanks, the excavated soil piles, and the piping area located between tank 15T and building 36.
- No concentrations of total petroleum hydrocarbons (TPH), benzene, toluene, xylenes, ethylbenzene (BTXE), or hexavalent chromium were detected in soil samples collected from the excavation for tanks 9T and 10T.
- No concentrations of BTXE were detected in soil samples collected from the excavation for tanks 15T through 18T, the associated spoil piles, and the piping area near tank 15T.
- TPH concentrations were detected in soil samples collected from the spoil piles, beneath tanks 15T through 18T and the piping area near tank 15T.
- TPH concentrations detected from the spoil piles and piping area exceed the cited regulatory guidelines.
- Concentrations of chromium, nitrate, sulfate, and fluoride detected beneath tank 9T and the associated spoil pile were below cited regulatory criteria.

BACKGROUND

The project site is located southwest of the intersection of Normandie Avenue and 190th Street in Torrance, California (see Figure 1). Tanks no. 9T and 10T were located north of DAC building no. 66. Tanks no. 15T through 18T were located between DAC buildings no. 1 and 36.

EMCON prepared a workplan for the removal of tanks 9T, 10T, and 15T through 18T (EMCON, January 21, 1991). During a June 19, 1991 meeting, DAC requested an additional scope of work which was incorporated into EMCON's revised workplan (EMCON, August 30, 1991). The additional tasks requested by DAC included:

- removal of 2 vadose wells (9TW and 10TW) located adjacent to tanks 9T and 10T
- closure of a surface runoff drain adjacent to tank 9T
- removal of a concrete wash slab near tank 15T`

According to DAC, the following constituents were previously stored in these tanks:

waste acid	tank 9T (5,000 gallon)	•
waste water, oil, and soap	tank 10T (10,000 gallon)	•
waste solvents	tank 15T (3,000 gallon)	6
trichloroethane	tank 16T (5,000 gallon)	•
trichloroethane	tank 17T (5,000 gallon)	•
methylene chloride and isopropyl alcohol	tank 18T (5,000 gallon)	

Analytical data provided by DAC for soil borings and vadose wells located in the immediate vicinity of tanks 15T through 18T indicate that concentrations of methylene chloride, 1,1,1-trichloroethane, trichloroethylene, toluene, xylenes, and ethylbenzene were detected at depths ranging from approximately 5 to 20 feet below grade (see Attachment 1). The location of the DAC soil borings and vadose wells are shown in Figure 2. It is EMCON's understanding that assessment of this area is currently under the jurisdiction of the California Regional Water Quality Control Board (RWQCB). Soil samples collected from this area by EMCON were analyzed for those compounds specified by the Los Angeles City Fire Department (LACFD).

TANK REMOVAL

Tank excavation and soil sampling activities were conducted under the jurisdiction of the Los Angeles City Fire Department (LACFD), permit no. 1856. A copy of the permit is included in Attachment 2.

Tanks 9T, 10T, and 15T through 18T were excavated by Disposal Control Service (DCS), under the supervision of EMCON during October 11 and 12, 1991. During excavation of tanks 9T and 10T, vadose monitoring wells 9TW and 10TW were removed and the adjacent concrete surface drain was backfilled. During excavation of tank 15T the concrete wash slab was removed. The tank interiors were high pressure cleaned in compliance with LACFD requirements. The rinseate liquids from tank 9T were removed by DCS and transported to Norris Industries, in Los Angeles, California (see Attachment 3). Rinseate liquids from tank 10T were transported by DCS to Chem-Tech Systems, Inc. in Vernon, California. Rinseate from tanks 15T through 18T were stored on site pending future consideration of disposal options. Prior to transport all

Mr. Boramy Ith April 27, 1992 Page 4

tanks were certified as clean by CTL Environmental Services of Harbor City, California (see Attachment 4). Following certification the tanks were transported by DCS to American Metal Recycling, Ontario, California to be destroyed for scrap purposes (see Attachment 5).

Excavated soils related to tanks 9T and 10T were stockpiled on site for subsequent disposal by DAC. Excavated soils from tanks 15T through 18T were returned to the excavation following tank removal, pending further site assessment as requested by the LACFD and DAC. Clean gravel and soil was used as backfill in the excavations to account for the volume of removed tanks and soil. Backfilled soils were compacted to approximately 90 percent relative compaction as certified by Duco Engineering, Inc. of Walnut, California (see Attachment 6). The excavations were completed with approximately 6-inch-thick asphalt surfacing.

SOIL SAMPLING

Soil samples from both excavations and the spoil piles were collected by EMCON under the direction of the LACFD. Soil sampling procedures are included in Attachment 7.

Tanks 9T and 10T

A total of five soil samples (DAC-06 through DAC-10) were collected beneath tanks 9T and 10T for laboratory analysis (see Figure 2). In addition a total of four soil samples (DAC-15 through DAC-18) were collected from the associated spoil piles.

Tanks 15T through 18T

A total of five soil samples (DAC-01 through DAC-05) were collected beneath tanks 15T through 18T (see Figure 3). Three soil samples (DAC-12 through DAC-14) were collected from the associated spoil pile. One sample (DAC-11) was collected beneath excavated piping located between tank 15T and building no. 36.

LABORATORY ANALYSES

All soil samples were analyzed by a California-certified analytical laboratory for compounds specified by the LACFD as follows:

 Soil samples collected from beneath tanks 10T, 15T through 18T, and the spoil piles were analyzed for total petroleum hydrocarbons (TPH) by U.S. EPA Method 8015.

PJC\C340801C.DOC

 All soil samples were analyzed for benzene, toluene, xylenes, and ethylbenzene (BTXE) by U.S. EPA Method 8020.

In addition to the above analyses required by the LACFD, soil samples collected from beneath tank 9T and the associated spoil pile were analyzed for compounds previously contained in tank 9T. These additional analyses, completed according to EMCON's revised workplan (August 30, 1991) included:

- total chromium by U.S. EPA Method 7190
- anion scan for nitrates, sulfates, and fluorides by U.S. EPA Method 300.0 modified

At the request of DAC sample DAC-10, collected beneath tank 9T, was analyzed for soluble threshold limit concentration (STLC) hexavalent chromium by U.S. EPA Method 7197.

The certified analytical reports and chain-of-custody documentation are included in Attachment 8.

FINDINGS

Tanks 9T and 10T

As shown in Table 1, no concentrations of TPH (<10 mg/kg) or BTXE (<0.005 mg/kg) were detected in soil samples collected from beneath tanks 9T and 10T (DAC-06 through DAC-10). In addition no concentrations of BTXE were detected in soil samples collected from the spoil piles (DAC-15 through DAC-18). TPH concentrations (up to 4,100 mg/kg) were detected in soil samples DAC-15 through DAC-18 collected from the spoil piles.

No concentrations of hexavalent chromium (<0.10 mg/L) were detected in sample DAC-10.

Concentrations of total chromium (up to 160 mg/kg), nitrate (27 mg/kg), sulfate (up to 250 mg/kg), and fluoride (66 mg/kg) were detected in soil samples collected from beneath tank 9T (DAC-09 and DAC-10). Concentrations of total chromium (450 mg/kg) and sulfate (1,000 mg/kg) were detected in soil sample DAC-15, collected from the spoil pile associated with tank 9T.

Tanks 15T through 18T

BTXE concentrations (<0.005 mg/kg) were not detected in soil samples collected from beneath tanks 15T through 18T (DAC-01 through DAC-05), the spoil pile (DAC-12 through DAC-14), and the piping between tank 15T and building no. 36 (DAC-11). TPH concentrations were detected in soil samples collected from beneath tanks 15T through 18T (up to 45 mg/kg), the spoil pile (up to 73 mg/kg), and the piping area (700 mg/kg).

REGULATORY CRITERIA AND GUIDELINES

Soil regulatory criteria and guidelines are discussed below and summarized in Table 1.

Total Threshold Limit Concentrations

The California Code of Regulations (CCR), Title 22, Division 4.5 establishes numerical criteria to determine if a waste should be considered hazardous (CCR, May 1991). These criteria include the total threshold limit concentration (TTLC) which is the total concentration of a substance (in a solid material), which is considered hazardous for the purpose of disposal. A solid waste with a concentration of a specific element or compound equal to or above the TTLC is considered a hazardous waste because of the persistent and bioaccumulative nature of the specific toxic substance present.

TTLC values are not defined for constituents detected in soil samples DAC-01 through DAC-18 with the exception of chromium and fluoride. Concentrations of these two constituents were all below the respective TTLC values.

Soluble Threshold Limit Concentration

The California Code of Regulations (CCR), Title 22, Division 4.5 establishes numerical criteria to determine if a waste should be considered hazardous (CCR, May 1991). These criteria include the soluble threshold limit concentration which is the soluble concentration (mg/L) of a substance (in a liquid) which is considered hazardous for the purpose of disposal. A solid waste which, after treatment with the waste extraction test (WET), produces dissolved concentrations of specific substances in excess of their STLCs is considered a hazardous waste because of the extractable and persistent bioaccumulative nature of the specific toxic substance present.

Soil Ingestion Screening Values

Soil ingestion Screening Values (SSVs) are used by Cal-EPA as a preliminary method to assess whether or not significant impact has occurred to soils at a site (DHS, June 22, 1990). SSVs can be used to show that a site is not significantly impacted, leading to an issuance of "No Further Action" determination by the DHS. However, SSVs cannot be used as site cleanup levels and pertain only to human health risk, not environmental risk. Therefore a site with low SSVs may require remediation as determined by the DHS. Concentrations of compounds in soils which exceed an SSV but are below background are assumed to indicate the naturally occurring concentrations of these compounds.

SSVs are not defined for the compounds detected in soil samples DAC-01 through DAC-18 with the exception of chromium, nitrate, fluoride. Concentrations of these three compounds were all below the respective SSVs.

Petroleum-Hydrocarbon Guidelines

Guidelines have been established by the RWQCB-Lahontan Region for petroleum-hydrocarbon impacted soils (RWQCB, January 7, 1987). Soils with petroleum-hydrocarbon concentrations that exceed 1,000 mg/kg commonly require removal, remediation, or a justification as to why removal or remediation are not warranted. Soils with petroleum-hydrocarbon concentrations between 100 and 1,000 mg/kg are typically reviewed on a case-by-case basis to assess if removal or remediation is necessary. Removal of soils with petroleum-hydrocarbon concentrations less than 100 mg/kg is generally not required by the RWQCB. Waste oil cleanup standards are decided on a case-by-case basis. These guidelines are sometimes used by other regulatory agencies.

TPH concentrations exceeding the RWQCB guidelines were detected in soil samples collected from the spoil piles associated with tanks 9T and 10T (DAC-15 through DAC-18) and from the piping area near tank 15T (DAC-11). Disposal of excavated soils from these areas was subsequently managed by DAC.

CONCLUSIONS

Based on our findings, EMCON presents the following conclusions:

 No concentrations of TPH, BTXE, or hexavalent chromium were detected in soil samples collected beneath tanks 9T and 10T.

PJC\C340801C.DOC

- No concentrations of BTXE were detected in soil samples collected from the spoil piles, beneath tanks 15T through 18T, or the piping area near tank 15T.
- TPH concentrations were detected in soil samples collected from the spoil piles beneath tanks 15T through 18T, and the piping area near tank 15T.
- TPH concentrations detected from the spoil piles and the piping area exceed the cited regulatory guideline.
- Concentrations of chromium, nitrate, sulfate, and fluoride were detected beneath tank 9T and the associated spoil pile and are below the cited regulatory criteria.

The closure assessment and report were performed and prepared using generally accepted consulting and engineering procedures and practices, and within the limits described in Attachment 9.

If you have any questions regarding the report please do not hesitate to call us at (818) 841-1160.

Sincerely,

EMCON Southwest

Scott N. Sanhan

Scott N. Sankey

Project Geologist

Keith G. Farrell

Director of Geology

SNS/KGF:keb

Mr. Boramy Ith April 27, 1992 Page 9

Attachments: References

Table 1 - Summary of Soil Analytical Results

Figure 1 - Site Location Map

Figure 2 - Location of Tanks 9T and 10T Figure 3 - Location of Tanks 15T through 18T Attachment 1 - Analytical Data From DAC Soil

Borings 15TB and 17TB and Vadose

Wells B-6 through B-8

Attachment 2 - Los Angeles City Fire Department - Tank Removal Permit

Attachment 3 - Uniform Hazardous Waste Manifests for Rinseate Liquids

Attachment 4 - Certified Industrial Hygienist Certificate

Attachment 5 - Certification of Tank Disposal

Attachment 6 - Compaction Report - Tank Excavation Backfill

Attachment 7 - Soil Sampling and Tank Removal Monitoring

Attachment 8 - Certified Analytical Report and Chain-of-Custody Documentation

Attachment 9 - Limitations

cc: Inspector Don Smith,

Los Angeles City Department of Fire

REFERENCES

- CCR, May 1991, California Code of Regulations, Title 22, Division 4.5, 1991.
- DHS, June 22, 1990, Interim Guidelines for Preparation of a Preliminary Endangerment Assessment Report: California Department of Health Services.
- EMCON, August 30, 1991, Workplan for Underground Storage Tank Removal, Douglas Aircraft Company, Torrance Facility (C6), 19503 South Normandie Avenue, Torrance, California: EMCON Associates, Burbank, California (project no. C34-08.01).
- EMCON, January 21, 1991, Transmittal of Bid No. C1-151-7BD-032: EMCON Associates, Burbank, California (project no. C34-08.01).
- Federal Register, Volume 55, No. 134, July 27, 1990, 40 CFR Parts 264, 265, 270, and 271 Corrective Action for Solid Waste Management Units at Hazardous Waste Management Facilities; Proposed Rule.
- RWQCB, January 7, 1987, Guidelines for the Disposal of Effluent from Fuel and/or Solvents Contaminated Ground-Water Treatment Systems and Cleanup of Petroleum Hydrocarbon Contaminated Soils: California Regional Water Quality Control Board Lahontan Region.

TABLE 1 SUMMARY OF SOIL ANALYTICAL RESULTS Douglas Aircraft Company Torrance Facility (C6) 19503 South Normandie Avenue, Torrance, California

Sample No.	Location	Date Sampled	TPH (1) (mg/kg)	Benzene (2) (mg/kg)	Toluene (2) (mg/kg)	Total Xylenes (2) (mg/kg)	Ethyl- benzene (2) (mg/kg)	Total Chromium (3) (mg/kg)	Nitrate (4) (mg/kg)	Sulfate (4) (mg/kg)	Fluoride (4) (mg/kg)	STLC Hexavalent Chromium (5) (mg/L)
DAC-01		10/19/91	<10	<0.005	<0.005	<0.005	<0 005					
DAC-02		10/19/91	45	<0.005	<0.005	<0.005	<0.005	- •				
DAC-03	excavation (15T - 18T)	10/19/91	<10	<0.005	<0.005	<0.005	<0.005			- •	••	
DAC-04		10/19/91	28	<0.005	<0.005	<0.005	<0 005					
DAC-05		10/19/91	<10	<0.005	<0.005	<0.005	<0 005				• •	
DAC-06		10/19/91	<10	<0.005	<0.005	<0.005	<0.005					
DAC-07	excavation (10T)	10/19/91	<10	<0.005	<0.005	<0.005	<0 005					
DAC-08		10/19/91	<10	<0.005	<0.005	<0.005	<0.005					
DAC-09	excavation (9T)	10/19/91		<0.005	<0.005	<0.005	<0.005	23	<10	12	66	• •
DAC-10	Oxodiadon (51)	10/19/91		<0.005	<0.005	<0.005	<0.005	160	27	250	<25	<0.10
DAC-11	piping (15T)	10/19/91	700	<0.005	<0.005	<0.005	<0.005		•-			
DAC-12		10/19/91	73	<0.005	<0.005	<0.005	<0.005					
DAC-13	spoil pile (15T-18T)	10/19/91	24	<0.005	<0.005	<0.005	<0.005		••			

BOE-C6-0182170

anac Kajj 4/8/92

TABLE 1 SUMMARY OF SOIL ANALYTICAL RESULTS Douglas Aircraft Company Torrance Facility (C6) 19503 South Normandie Avenue, Torrance, California

Sample No.	Location	Date Sampled	TPH (1) (mg/kg)	Benzene (2) (mg/kg)	Toluene (2) (mg/kg)	Total Xylenes (2) (mg/kg)	Ethyl- benzene (2) (mg/kg)	Total Chromium (3) (mg/kg)	Nitrate (4) (mg/kg)	Sulfate (4) (mg/kg)	Fluoride (4) (mg/kg)	STLC Hexavalent Chromium (5) (mg/L)
DAC-14	spoil pile (15T-18T)	10/19/91	<10	<0.005	<0.005	<0.005	<0.005				· -	
DAC-15		10/19/91	2900	<0.005	<0.005	<0.005	<0.005	450	<10	1000	<25	
DAC-16	and discount to the	10/19/91	4100	<0.005	<0.005	<0.005	<0.005		- ,-			
DAC-17	spoil piles (9T-10T)	10/19/91	57	<0.005	<0.005	<0.005	<0.005					• •
DAC-18		10/19/91	1200	<0.005	<0.005	<0.005	<0.005	- •				
	riteria and Guidelines:											
	7	TTLC (6)	nc	nc	nc	nc	nc	2500	nc	nc	18,000	500
	S	STLC (7)	nc	nc	nc	nc	nc	560	nc	nc	180	5
	S	SSV-chronic (8)	nc	nc	nc	nc	nc	1,000,000	1,000,000	nc	80,000	nc
		SSV-5year (8)	nc	nc	nc	nc	nc	2,000	2,000	nc	100	nc
	F	RWQCB (9)	100	nc	nc	nc	nc	nc	nc	nc	nc	nc

Soil samples analyzed by Golden State Analytical Services, Inc., Van Nuys, California.

nc = no criteria or guideline established

- (1) TPH (Total Petroleum Hydrocarbons) analyzed using U.S. EPA Method 418.1
- (2) Analyzed using U.S. EPA Method 8020.
- (3) Analyzed using U.S. EPA Method 7190.
- (4) Analyzed using U.S. EPA Method 300.0m.
- (5) Analyzed using U.S. EPA Method 7197.
- (6) = Total Threshold Limit Concentration (California Code of Regulations, Title 22, Division 4.5).
- (7) = Soluble Threshold Limit Concentration, in mg/L (California Code of Regulations, Title 22, Division 4.5).
- (8) = Soil Ingestion Screening Values (Interim Guidance for Preparation of a Preliminary Endangerment Assessment Report, State of California Department of Health Services, June 22, 1990).
- (9) = Petroleum Hydrocarbon Guidelines, in mg/kg (California Regional Water Quality Control Board, Lahontan Region, January 1987).

BOE-C6-0182171

QAQC XM) 4/8/92


⁻⁻⁼ not analyzed.



DOUGLAS AIRCRAFT COMPANY TORRANCE FACILITY (C6) 19503 S. NORMANDIE AVENUE TORRANCE, CALIFORNIA

SITE LOCATION MAP

PROJECT NO. C34-08.01






DOUGLAS AIRCRAFT COMPANY TORRANCE FACILITY (C6) 19503 S. NORMANDIE AVENUE TORRANCE, CALIFORNIA

LOCATION OF TANKS 9T AND 10T

FIGURE

PROJECT NO.

C34-08.01





DOUGLAS AIRCRAFT COMPANY TORRANCE FACILITY (C6) 19503 S. NORMANDIE AVENUE TORRANCE, CALIFORNIA

LOCATION OF TANKS 15T THROUGH 18T

FIGURE

3

PROJECT NO.

C34-08.01

ATTACHMENT 1

ANALYTICAL DATA FROM DAC SOIL BORINGS 15TB AND 17TB AND VADOSE WELLS B-6 THROUGH B-8

. EMCON Southwest.

SAMPLE NO (Date)	DEPTH (Ft)	OVA	MEK	111-TCA						
15TB		<u> </u>		111-1CA	TCE	TOLUENE	ETHYL BENZENE	TOTAL XYLENES	MIBK	1,4-DIOXANE
	5	52								
(8-24-87)	10	600	0.57	ND	ND	0.056	0.011	0.11	ИD	ND
	15	1000+	160	27	10	870	41	460	DI/I	ND
	20	1000+	1800	38	94	6300	180	1300	ИD	ND
17TB	5	200	ND	ND	C71	11D	ND	ND	ND	11D
(8-24-87)	10	30	ND	0.036	ND	ND	ND	11D	13D	ND
	15	45								
	20	60	ИD	0.013	ND	IJD	11 D	ИD	ИD	11D
В-6	5	120								
(6-13-89)	10	1000+	ND	ND	0.016	0.064	0.001	0.009	ND	ND
,	15	1000+								
	20	1000+	ND	12	45	1900	51	390	ND	MD
B-7	5	80								
(6-13-89)	10	90								
	15	90								
	20	110				-				
B-8	5	47	***	· 	******		<u></u>			ton the first
(6-14-89)	10	42								
	15	45								
	20	20				 ,				

NOTE: ND- None Detected, --- Not Analyzed at that Depth

ATTACHMENT 2

LOS ANGELES CITY FIRE DEPARTMENT TANK REMOVAL PERMIT

- EMCON Southwest.

09-12-92 Expires .

10

PERMIT

Exempt-714 Fee Paid ...

-.2/12

In accordance with terms of the application on file with the Fire Prevention Bureau, permission is MUST COMPLY WITH FPB REQUIREMENT NO. 41 Name Douglas Aircraft Company Disposal Control Service Incorporated Mail 1369 West 9th Street Upland, CA 91786 Abandon 6 atmospheric tank(s) as per plans and specifications submitted to the Fire Prevention Bureau and subject to the field inspector's approval at the site Location BY ORDER OF CHIEF ENGINEER 19503 South Normandie Avenue

ATTACHMENT 3

UNIFORM HAZARDOUS WASTE MANIFESTS FOR RINSEATE LIQUIDS

EMCON Southwest.

20	ARIT OF TYPE. (FORM DESIGNED TOP BOST OFF BOST			•			Secretario, Cano	
A	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA 10 1 CIAIDIOI 816151		lenifest ument No. Z	2. Page 1	1 .	n in the sheded areas: uired by Federal law.	
	3. Generator's Name and Mailing Address		n: R. Tue		A. State Manife			_
	Douglas Aircraft Co	mpuny mi	lode: C6-	7	·	^	79462 -	
	19503 S. Normand;	Avenue		37	B. State Gener			_
	19503 S. Normand:	2926 OR (2	13) 5 33 - 72	231	HIAIN	01361	010151619181	٠,٠
į	5. Iransporter 1 Company Name	6.	US EPA ID Number		C. State Trans		71 10511	
	Disposal Control Ser	vice 10A	TI 98 0101314	4/1814	D. Transporter	e Phone /	- 800-824-33	44
	7. Transporter 2 Company Name	8.	US EPA ID Number		E. State Trans	and the second second second second		
			11111	111	F. Transporter	s Phone		
	9. Designated Facility Name and Site Addre	88 10.	US EPA ID Number	-	G. State Facili	ly's ID	:	
	Norris Industries	1000 11 12	NET 10-18-				11111	
	5215 S. Boyle A		D097039	993	H. Facility's Pr	ione		
	Las Anueles. CA	90058 F	ने भेरी भेरी हो।	न्द्रान्त	213	<u> </u>	-7///	
	11. US DOT Description (Including Proper S	hipping Name, Hazard Class.	and ID Number)	12. Cont		Total Juantity	14. I. Unit Wests No.	
				No.	Туре		/t/Vol	
	*RQ, Waste Corros (Nitric Acid) Corro	ive Liquidy	N.O.S.				State 792	
	(Nitric Acia) Corro	isive Majeric	13 UN 1760	20.01	T. T C		CD 4 (O4)	-
	(2002 DOOT)	A CONTRACTOR OF THE PROPERTY O		10101	TITOG	21019		27
						İ	State	
				1		1	EPA/Other	
	C.			1.1			State	بيحنبيس
							0.2.0	
				1			EPA/Other	
	d.			+			State	mmere-
				1 1	1 1 1		EPA/Other	
	J. Additional Descriptions for Materials Liste	d Above		•	K. Handling C	odes for Wa	stes Listed Above	
	a) Acceptance = E-1	062 CRZ. W45	te Mixed Aci	ds	a.		b.	
	(a) Acceptance # E-1 Waste Generated f Tunk Removal.	rom lank 91	undergran	ina				
	Nitric acid 0-10	% Hydraflaar	c acid o-1	%	c.		d.	
	Nitric acid 0-10 Chromic acid 0-6	of Phorides	32 - 100%	.			•	
	i 15. SORCIBI Mandling Instructions and Additio	and Intermedian			-474-	9300	o Do not was	<u>~</u>
	into sewer or W.	aterway. De	not bred	the W	porso	工产	unable to	~,
	In case of accident into sewer or war deliver return to	generature	Volume is	s app	roxima	te. I	DOT Emerger	7 (i
	Response Guide #	50. FH P	ormit No.	4-	9/0524	02.1	Warris Shoul-	ľ
	16. bill Disposal Con	tral Service	for dispos	a/.			•	•
	GENERATOR'S CERTIFICATION: I her and are classified, packed, marked, and	reby deciare that the content I labeled, and are in all respe	s of this consignment are cts in proper condition for	s fully and ac	curately describ	ed above by	r proper shipping name	t
	mational government requisitons.							
	If I am a large quantity generator, I certi to be economically practicable and that							• •
	present and future threat to human heal generation and select the best waste m				ave made a goo	d faith effort	to minimize my waste	•
	Printed/Typed Name		Signature	Can anorg.				<u>. ` '</u>
	Robert G. Tuel	1. Tr.	-01 1	2 =7	MA		Month Day Yes	er 1
	17. Transporter 1 Acknowledgement of Reco		1406/	1. J.	reck, Gr	1	1/10/1919	
	Printed/Typed Name		Signature /				Month Day Ye	
	1 and flaces	م د		16 1			Month Day Ye	er . /
	18. Transporter 2 Acknowledgement of Reco	sipt of Materials	1 (Enl)	<u> </u>	/ 1 -		1/9/139	4
	Printed/Typed Name		Signature		<i>/</i> ·		Month Day Ye	
					***	•	MONII DEY 19	887
	19. Discrepancy Indication Space		· ·					***************************************
					• , •	ı		
							ر مورد د م	• • •
			•					
	20. Facility Owner or Operator Certification	of receipt of hazardous mate	rials covered by this ma	nifest excep	as noted in Ite	m 19		December
	Printed/Typed Name		Signature		1//	1 11	Month Day Ye	er
	inffuren mutsp	LKLDARA	it aton		Mute	Rus	- MA1919	1
,	A (1/88) -		**************************************					سأححد

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

ATTACHMENT 4 CERTIFIED INDUSTRIAL HYGIENIST CERTIFICATE

_ EMCON Southwest_

IANK CERTIFICATION REPORT

4	CTL ENVIRONMENTAL SERVICES	
~	24404 S. Vermont Avenue #207	
•	Harbor City, CA 90710	
٠-	TEL.: (213) 530-5006	
	r garage and the first term of the second state of the second second second second second second second second Second second	*

02655 TANK REMOYAL CERTIFICATE F:

TANK DESCRIPTION	TANK SIZE	TANK	TANK	RESULTS OF TANKS
DEGOKIP NOW		NUMBER	CONTENTS	INSPECTION :
U.C. Steel	10 000 callon		wask wakenlail/stap	LEL 19
U.C. Steel	5000 mellon		acid wash	LEL OZ
U.E. Skel	5,000 pllon		137	LEL OR
U.C. S/21	5,000 -41/0-		HT	
U.C. Stel	5000 della-		ICT	LELOR
U.C. Shed	\$000 gellon		157	LEL 0%

The tank(s) described above has/have been inspected and found to be gas free based on readings obtained with an MSA type 2A Explosivity Meter (LEL of zero percent). A visual inspection has been made of the interior of the tank(s) and no visible contamination has been observed except as noted below. EXCEPTION: The tank(s) described above is/are approved for removal and transportation. CERTIFIED BY: STUART E. SALOT CERTIFIED INDUSTRIAL HYGIENIST CLIENT COPY CTL COPY FIRE DEPARTMENT COPY TRANSPORTERS COPY TRANSPORTERS COPY Pink

BOE-C6-0182183

Goldenrod

ATTACHMENT 5 CERTIFICATION OF TANK DISPOSAL

_ EMCON Southwest _

AMERICAN FUEL YAME	No. 37820
METAL RECYCLING, INC.	TANK DISPOSAL FORM
2202 South Milliken Avenue Ontario, CA 91761	Date: 10-21 39-71
(714) 988-8000	POS
ADDRESS: 13/9	St. Voland CA 91786
	ougles Calif
DESTINATION: A.M.R. 2202 S. M.	illiken Ave., Ontario, CA 91761
CANTE TIME PROJECTED TANKE	Oeccaso Pro
SPECULINET RUST COM	TIME IN KEDIECES JENK TIME DUT DISPOSAL FORM
	#37725
Services Rendered ——Cost	TANKS RECEIVED
Disposal res 20000 Extensive Loading Time 150,000	GTY = GALLONS TYPE NETTONS TOTAL
Disposal Fee with Permit 300.00	No. of the second secon
Fiberglass Tank Disposal Fee Per Tank 40000 Fiberglass Tank Delivered 20000	1000-11
Bobtail Disposal Fee 250.00	2.4
TOTAL CHARGES S	7,500
All fees incurred are per load unless specified. Terms are net 30 days from date of invoice. Contractor's signature represents acceptance	12000 🗓 😅
of terms for payment, and confirms that tank removal complies with State laws.	NO. OF TANKS TOTAL NET TONS
CONTRACTOR'S SIGNATURE	*F - FIBERGLASS (S - STEEL 105)
· ····································	OF TANK DISPOSAL / DESTRUCTION INCE OF THE TANKS) AS SPECIFIED ABOVE. ALL MATERIALS SPECIFIED ABOVE. ALL MATERIALS SPECIFIED ABOVE. ALL MATERIALS SPECIFIED DESTROYED FOR SCRAP PURPOSES ONLY. DATE

CONTRACTOR COPY

CONTRACTOR COPY

BOE-C6-0182186

RECYCLING, INC.	<i>)</i>	7	ANK	DISP	DSAL	_ FOF
2202 South Milliken Avenue			Date:	lo-	-21:	.19 5
Ontario, CA 91761		* , ***	Job#		1	
(714) 988-8000	No. 1 .	₩	P.O.#			• •. •.
CONTRACTOR DIS DUSAL	TA.	man l		•		
ADDRESS: 9.78		-10	MAD	· · · Par		•
JOS SITE		7	, , , , , , , , , , , , , , , , , , ,	1376	, .	
ADDRESS:		SLAS		PRANCE	- 0	
DESTINATION A SA E TOO						
DESTINATION A.M.FL.220		en Ave., C	ritario,	OWNERED BA		LIC NO.
The second secon	TRAE	Anta-St.	7.13-			
SPECIAL INSTRUCTIONS				The second se	ار المعادل الم المعادل المعادل المعاد	
	TIME	Out -			27.33	** **
	V	45		UL. TIL	- 4 - 4	
Services Rendered (Cost	<u> </u>	ر ستان د معاشرهای در	W		-
Prince Control		-	guaren 199 <mark>0.</mark> Agai		· • • · .	* .
Disposal Fee	20000	***	TANKS	RECEIVED	NETT	ONS TO
Extensive Loading Time	150.00	MY "	GALLON	P 8		CASS II
Disposal Fee with Permit	300.00	NA CONTRACTOR	260 Sano 7/27			.14
Finerglass Tank Disposal Fee Per Tank	1 " "	500 m	540] 	.24
* * * * * * * * * * * * * * * * * * *	27-14-7	4. Tag (- 5. 4. 5.)	1000 - 6 R		ana waa waa waa waa waa waa waa waa waa	.61
Cars to 1	111725		2000		de alexandra de la como br>La como de la como d	97 97
Bobtail Disposal Fee	23000		3000		ANN THE PROPERTY.	132 /-
_CARSCHITCHTEE Del -	EMONO.		5000			242
TOTAL CHARGES \$ =	3	3=24,0=4,1 4	7800			126
All fees incurred are per load unless spe			9000			195
Terms are net 30 days from date of invoice	56.		12000 12000			493
Contractor's signature represents accept of terms for payment, and confirms that		OF TANKS		TOTAL	NET TO	ONS
removal complies with State laws.		1			· - · ·	32
					/	
CONTRACTOR'S SIGNATURE	'F	- FIBERGL	A5S	STEEL	105	
CERTIF	ICATE OF TA	NK DISPOSA	L / DESTR	CIFIED ABOVE	municipal de la constantina della constantina de	

77 (3) P

BOE-C6-0182187

AMERICAN FUEL TANK METAL	Na. 37727
RECYCLING, INC.	TANK DISPOSAL FORM
2202 South Milliken Avenue Ontario, CA-91761	Date: 10-21 ,19 91
(714) 988-8000	P.O.#
CONTRACTOR DISPOSAL (persol
ADDRESS:	OPLAND CAL
JOB SITE ME DOUMED	DOUSLAS
ADDRESS 19503 NORMA	SDIS AV. TORRANCE CH.
	Milliken Ave., Ontario, CA 91761
DATE PROJECTED WARE	GROPARD IN LIG. NO.
	TIME IN:
SPECIAL INSTRUCTIONS	TIMEOUT
Services Rendered Cost	
Disposal Fee 20000	TANKS RECEIVED
Extensive Loading Time 150.00	QTY GALLONS TYPE NETTONS TOTAL
Disposal Fee with Permit 300.00	260 🗓 🗖
Fiberglass Tank Disposal Fee Per Tank 40000	580 D D 24
	1000 - € 12
Fiberglass Tank Delivered 200.00	27
Bobtail Disposal Fee 250.00	1.32
_ Conscious Fee Dec 25080	24 2.4
TOTAL CHARGES \$_ ~ ~	7500 3.26
All fees incurred are per load unless specified	9000
Terms are not 30 days from date of invoice. Contractor's signature represents acceptance	12000 🖸 🗘 +93
Aminimum a mainimum inhibaniisa annahlasing	NO. OF TANKS TOTAL NET TONS
of terms for payment, and confirms that tank removal complies with State laws.	
of terms for payment, and confirms that tank	2 6.75

CONTRACTOR COPY

7.75 12

ATTACHMENT 6 COMPACTION REPORT - TANK EXCAVATION BACKFILL . EMCON Southwest.

DUCO ENGINEERING. INC.

SOIL & GEOLOGIC INVESTIGATIONS FILL CONTROL - SOIL TESTING

20938 CURRIER RD. - WALNUT, CA 91789 (818) 964-3449 • (714) 594-7414 • FAX (714) 594-3853

October 28, 1991

Disposal Control Service 1369 W. Ninth Street Upland, California 91786

Subject: Report of Compaction Tests

Tank Removal Backfill

McDonald Douglas Facility

19503 S. Normandy Avenue

Torrance, California

Job No.: 1-206

Job No.: 1-206

Gentlemen:

In accordance with your request this firm has performed field density tests to determine the relative compaction of the soils used to backfill the two (2) tank removal excavations at the subject site.

Prio to placing the compacted fill, the tank excavations were brought to within 5.0 to 6.0 feet of finish grade with coarse gravel.

The results of these tests, taken in accordance with ASTM test method D1556 and their locations, shown on a sketch of the areas, are attached as a part of this report.

Maximum density and optimum moisture were determined for each type of soil in accordance with ASTM test method D1557-78T. The results of these determinations are as follows:

Maximum Density Soil Type 124.0 PCF A-Silty sand B-Fine to med. sand 108.5 PCF

Optimum Moisture 10.2% 10.6%

Based on the results of the field density tests, as reported herein, it is the opinion of this firm that the tank removal excavations have been properly backfilled and compacted.

Respectfully submitted,


DUCO ENGINEERING, INC.


BLDG 36

151 ° 1 167 ° 3177 187 8

BLDG 1







CLEANING

SLAB

DUCO ENGINEERING

29838 CURRIER ROAD . WALNUT, CALIFORNIA 91788



LOCATION OF 2 TEST

WAT FILL SCALE I"= 20'
WAT AREA JOB NO. 1-206
FIGURE NO. 2

DUCO ENGINEERING, INC.

دسو د		SUMA	SUMMARY OF FIELD DENSITY TESTS					
Test No.	Date	Location	Depth	% Moist.	Dry Den. P.C.F.	Soil Type	% Comp.	
· ·	10-24-91	North Tanks	-3'	8.3	107.0	A	86.3	
;	H	North Tanks	retest of #1	9.6	117.1	·· A	94.4	
3	10-25-91	North Tanks	FG	5.8	114.7	A	92.5	
1	11	South Tanks	-5.5'	3.8	102.1	В	94.1	
3	11	South Tanks	-4.0'	3.9	99.7	В	91.9	
5-	10-26-91	South Tanks	-2.01	9.4	104.7	В	96.5	
7	41	South Tanks	FG	14.9	105.4	В	97.1	

ATTACHMENT 7 SOIL SAMPLING AND TANK REMOVAL MONITORING EMCON Southwest_

ATTACHMENT 7 SOIL SAMPLING AND TANK REMOVAL MONITORING

Soil samples were collected by pushing 4-inch long by 2-inch diameter brass rings into soil lifted by clam-shell or backhoe from specific locations in each excavation. Each sample was collected from native soil below the fill material approximately 1 to 2 feet below each tank. At each sampling interval one full brass liner was collected, sealed with Teflon tape and plastic end caps, and properly labelled. The sample was then placed on ice and transported to a California-certified laboratory along with appropriate chain-of-custody documentation.

The PID was also utilized along with a combustible gas indicator and Draeger tubes to detect the presence of potentially harmful constituents in the breathing zone of site personnel as specified in the site health and safety plan.

ATTACHMENT 8 CERTIFIED ANALYTICAL REPORT AND CHAIN-OF-CUSTODY DOCUMENTATION

EMCON Southwest -



Analytical Services, Inc.

15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

October 29, 1991

Mr. Scott Sankey EMCON Southwest 3300 N. San Fernando Blvd. Burbank, Ca. 91504

RE: Douglas Aircraft / C34-08.01

Dear Mr. Sankey:

Enclosed are the results of the samples submitted to our lab on October 22, 1991. For your reference, our service request number for this work is 7568.

All analyses were performed in accordance with the laboratory's quality assurance program.

Please call if you have any questions.

Respectfully submitted:

My Lower ST

Dr. B. Gene Bennett

GOLDEN STATE ANALYTICAL SERVICES, INC.



Analytical Services, Inc. 15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

P.O.#:

Project Name:

Project#:

EMCON Southwest

Douglas Aircraft - Torrance

C34-08.01

N/A

Matrix:

Soil

Date Received: 10/22/91

Date Analyzed: 10/23/91

GSAS Job#:

7568

Total Petroleum Hydrocarbons (418.1)

mg/Kg (ppm)

Client Sample#	GSAS Sample#	Amount Detected	Reporting Limits
DAC - 01	GS-1091-1001	BRL	10
DAC - 02	GS-1091-1002	45	10
DAC - 03	GS-1091-1003	BRL	10
DAC - 04	GS-1091-1004	28	10
DAC - 05	GS-1091-1005	BRL	10
DAC - 06	GS-1091-1006	BRL	10
DAC - 07	GS-1091-1007	BRL	10
DAC - 08	GS-1091-1008	BRL	10

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett

William Kenny



Analytical Services, Inc. 15735-1 Strathern St. • Van Nuys • CA 91406

Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

Project Name:

Project#:

P.O.#:

EMCON Southwest

Douglas Aircraft - Torrance

C34-08.01

N/A

Matrix:

Soil

Date Received: 10/22/91

Date Analyzed: 10/23/91

GSAS Job#:

Total Petroleum Hydrocarbons (418.1)

mg/Kg (ppm)

Client Sample# GSAS Sample#		Amount Detected	Reporting Limits
DAC - 11	GS-1091-1011	700	10
DAC - 12	GS-1091-1012	73	10
DAC - 13	GS-1091-1013	24	10
DAC - 14	GS-1091-1014	BRL	10
DAC - 15	GS-1091-1015	2900	10
DAC - 16	GS-1091-1016	4100	10
DAC - 17	GS-1091-1017	57	10
DAC - 18	GS-1091-1018	1200	10

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett

1 1/1 La 130 - 4



Analytical Services, Inc.

15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

EMCON Southwest

Soil

Project Name:

Douglas Aircraft - Torrance

3011

Project#:

204 - - - -

Date Received: 10/22/91

P.O.#:

C34-08.01

Date Analyzed: 10/23/91

.#: N/A

GSAS Job#:

Matrix:

7568

Total Chromium (EPA 7190)

mg/Kg (ppm)

Client Sample#	GSAS Sample#	Amount Detected	Reporting Limits
DAC - 09	GS-1091-1009	23	2.5
DAC - 10	GS-1091-1010	160	2.5
DAC - 15	GS-1091-1015	450	2.5

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett

Not in the new



Analytical Services, Inc. 15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

Project Name:

Project#:

P.O.#:

EMCON Southwest

Douglas Aircraft - Torrance

C34-08.01

N/A

Matrix:

Soil

Date Received:

10/22/91

Date Analyzed:

10/23/91

GSAS Job#:

7568

Client Sample#	GSAS Sample#	Benzene ug/Kg (ppb)	Toluene ug/Kg (ppb)	Total Xylenes ug/Kg (ppb)	Ethyl Benzene ug/Kg (ppb)
DAC - 01	GS-1091-1001	BRL	BRL	BRL	BRL
DAC - 02	GS-1091-1002	BRL	BRL	BRL	BRL
DAC - 03	GS-1091-1003	BRL	BRL	BRL	BRL
DAC - 04	GS-1091-1004	BRL	BRL	BRL	BRL
DAC - 05	GS-1091-1005	BRL	BRL	BRL	BRL
DAC - 06	GS-1091-1006	BRL	BRL	BRL	BRL
D AC - 07	GS-1091-1007	BRL	BRL	BRL	BRL
DAC - 08	GS-1091-1008	BRL	BRL	BRL	BRL
D AC - 09	GS-1091-1009	BRL	BRL	BRL	BRL
Reporting Limits		5.0	5.0	5.0	5.0

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett



Analytical Services, Inc. 15735-1 Strathern St. • Van Nuys • CA 91406

Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

Project Name:

EMCON Southwest Douglas Aircraft - Torrance

C34-08.01

Project#: P.O.#:

N/A

Matrix:

Soil

Date Received:

10/22/91

Date Analyzed:

10/23/91

GSAS Job#:

7568

BTX & E (8020)

Client Sample#	GSAS Sample#	Benzene ug/Kg (ppb)	Toluene ua/Ka (ppb)	Total Xylenes ug/Kg (ppb)	Ethyl Benzene ua/Ka (ppb)
DAC - 10	GS-1091-1010	BRL	BRL	BRL	BRL
DAC - 11	GS-1091-1011	BRL	BRL	BRL	BRL
DAC - 12	GS-1091-1012	BRL	BRL	BRL	BRL
DAC - 13	GS-1091-1013	BRL	BRL	BRL	BRL
DAC - 14	GS-1091-1014	BRL	BRL	BRL	BRL
DAC - 15	GS-1091-1015	BRL	BRL	BRL	BRL
DAC - 16	GS-1091-1016	BRL	BRL	BRL	BRL
DAC - 17	GS-1091-1017	BRL	BRL	BRL	BRL
DAC - 18	GS-1091-1018	BRL	BRL	BRL	BRL
Reporting Limits	,	5.0	5.0	5.0	5.0

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett

1.1. - 1-1



Analytical Services, Inc.

15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

Client:

Project Name:

Project#: P.O.#:

EMCON Southwest

Douglas Aircraft - Torrance

C34-08.01

N/A

Matrix:

Date Received:

Date Analyzed:

10/22/91 10/23/91

Soil

GSAS Job#:

7568

Anion (EPA 300.0m)

mg/Kg (ppm)

Client Sample#: GSAS Sample#:	DAC - 09 GS-1091-1009	DAC - 10 GS-1091-1010	DAC - 15 GS-1091-1015	Reporting Limits
Nitrate	BRL	27	BRL	10
Sulfate	12	250	1000	10
Fluoride	6 6	BRL	BRL	25

BRL: Below Reporting Limit

Approved By: Dr. B. Gene Bennett

William -

GOLDEN STATE ANALYTICAL SERVICES, INC.

15735-1 Strathern St. Van Nuys, CA 91406 (818) 376-1122 • FAX (818) 781-8128

Chain of Custody Record Analytical Services Request

CLIENT NAME		ADDRESS/PHO	ONE/FAX		1. 44	,,,							/	
			By bank Blad		15/8161		,		LYSES R		TED		/ 756	JOB#
PROJECT NAME/LOCATION			CLIENT P.	ROJECT NO.					\. \. \. \. \. \. \. \. \. \. \. \. \. \	/ ,	/	/ ,	/ /	
Duglis Aircraft /				-08.01	/	/ ,	/ ,	/ /	1/2° /			' /		
PROJECT MANAGER	SAMPLER(S)/	P.O.	NO.	/	/	/	Ä	* /				/	
Scott Sentley	Rob	ert 61	ustr			\/u_	ال	4	9/					
SAMPLE IDENTIFICATION NO.	DATE	ТІМЕ	LAB SAMPLE NO.	SAMPLE MATRIX	MON!	87,8°	8/4	17. 12 M	CO Take Houng	//	/ /	REQUEST: TURNAROR TIME	REM	ARKS
DAC-OI	10/19/91		1091-1001	Soi !	/	~	ļ					4 day		8020 C
DAC-02			1002		/	/							UST	no priority
17A(-03			1003		/	V							Char	no priority
DAC-04			1004		/	1								
DAC-05			1005			/								
DAC-06			1006		/	~								
DAC-07			1007		/	/								
DAC-08			1008		/	/						_		
DA(-09			1009			V	V	/					7190 and	3000
DA C-10			1010			~	V	/		_			usults up	orkd
DA (-1)			1011		V	/							separately	hom
DAC-12	V		1012	<u> </u>	/	V		l				<u> </u>	4/8/1 - S	
RELINQUISHED BY, (Signature)			DATE - 21:41	TIME 8'COAN	1	VED BY	: (Signat	mue)					DAIB	IIME
RELINQUISHED BY: (Signature)			10-2/-9/ DATE	TIME9:50 am	RECEI	VED BY	: (Signat	ure)					DATE	ПМЕ
from Sanks			10-32-91 DATE	TIME										
RELINQUISHED BY: (Signature) RELINQUISHED BY: (Signature)	2011		DATE 10/72/90	TIME 12.35pm	RECEI	VED BY	(Signat	ure)	(1)				17/17/41	TIME 17:35 pm
SEND WOLF TO	varie		1017711	10 Jun	1-6		M	160					1.0/ rol	1 7.
					Unier	E COBV	· Acc-	npanies S	emple:					
									empres					
					YELL	OW COI	PY: San	npler						

GOLDEN STATE ANALYTICAL SERVICES, INC.

BOE-C6-0182205

15735-1 Strathern St. Van Nuys, CA 91406 (818) 376-1122 • FAX (818) 781-8128

Chain of Custody Record Analytical Services Request

CLIENT NAME		ADDRESS/PH	IONE/FAX	•		7							
EMCON.	Southwest	3300	N. Burban	K BlvJ. X(818)84	6-47	80/		ANA	LYSES RE	QUESTED		158	A8 JOB #
PROJECT NAME/LOCATION	· / / ·		CLIENT					1	\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		7		
Douglas Airera	tt /to	rrance	C 3	4-08.0		/		3,0			/ /		
PROJECT MANAGER	SAMPLER(S)	P.O). NO.	/	,	/ /	(h /,X	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	/ /	/ /	/	
Scott Sankey	Rob,	ert 6	laser		TRPH	_/,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		12 12 12 12 12 12 12 12 12 12 12 12 12 1		/ /			
SAMPLE IDENTIFICATION NO.	DATE	TIME	LAB	SAMPLE	Z PH	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		22	§] /	′ /	BBQUEST		
IDENTIFICATION NO.			SAMPLE NO.	MATRIX	/	/20	7 ^	Y V			TURNARON	REI	MARKS
DAC-13	10-19-91		1091-1013	Soi 1	_	-					4 days	4:8:1 1	8020 C
DAC-14			1014		/	1					1		
DAC-15			1015		1	~	/	1			Π	- 4	no priority
DA(-16			146		1	/							cg c
DA (-17			1017	1 1	1	/							
DAC-18			1018		1	/							
		~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	1010	<u> </u>								<u> </u>	
										_			
													······································
									_				
RELINQUISHED BY: Kignature)		T	DATE	TIME	RECEIV	CD DV	<u> </u>					5.455	
/W/		-		8:00 Am.	RECEIV	EDDI	: (Signau	ire)				DATE	TIME
RELINQUISHED BY: (Signature)				TIME 9:50 46	RECEIV	ED BY	(Signatu	ıre)				DATE	TIME
for Samly			10-22-91	12:15 m.	İ				$\overline{}$				
RELINQUISHED BY: (Signature)	~ 1/		DATE	TIME	RECEIV	EB BY	(Signal)	re)	フ _フ			DATE	TIME
A Samly RELINQUISHED BY: (Signature) SENDINVOIGE TO:	nu	· · · · · · · · · · · · · · · · · · ·	10/22/91	1235pm	16	11	[4]	a				ירןגאנטן	1'C-35 BM
prio involga to.												ľ	ĺ
					WHITE	COPY	: Accom	panies Sa	mples			· 7	
					YELLO	W COP	Y: Sam	pler					



Analytical Services, Inc.

15735-1 Strathern St. • Van Nuys • CA 91406 Tel: (818) 376-1122 • Fax: (818) 781-8128

November 04, 1991

Mr. Scott Sankey EMCON Southwest 3300 N. San Fernando Blvd. Burbank, Ca. 91504

RE: Douglas Aircraft / C34-08.01

Dear Mr. Sankey:

Enclosed are the results of the samples submitted to our lab on October 22, 1991. Request for additional analysis was phoned in by Keith Farrell on October 28, 1991. For your reference, our service request number for this work is 7568-A.

All analyses were performed in accordance with the laboratory's quality assurance program.

Please call if you have any questions.

Respectfully submitted:

Yoll will place

Dr. B. Gene Bennett

GOLDEN STATE ANALYTICAL SERVICES, INC.

GOLDEN STATE ANALYTICAL SERVICES, INC.

1568-4

15735-1 Strathern St. Van Nuys, CA 91406 (818) 376-1122 • FAX (818) 781-8128

Chain of Custody Record Analytical Services Request

CLIENT NAME		ADDRESS/PH	IONE/FAX												
ENCON 54 PROJECT NAME/LOCATION)		bank					AN	ALYSES	REQUI	ESTED		/ 74	GSAS JOB #	2
PROJECT NAME/LOCATION DOUG OS A) PROJECT MANAGER		· /		PROJECT NO. <u> </u>	0/		\					7/		<i></i>	
Scott Sankey		s) + G/a	P.C	D. NO.			' /								
SAMPLE IDENTIFICATION NO.	DATE	TIME	LAB SAMPLE NO.	SAMPLE MATRIX								REQUESTE TURNAROU.	D	REMARKS	
DAC - 10	10/19/91		109/- 1010	501/	$\perp X$									receive	
													10/22/9	V. Reque di Fiona	5/
														is called	
														Keith	1
				<u> </u>										(EMCON	7/
													to To	(OB))
														7-7	
DEL BIOLUCUED BY AC															
RELINQUISHED BY: (Signature)			DATE	TIME	RECEIV	ED BŸ:	(Signatu	ire)			(DATE	TIME	
RELINQUISHED BY: (Signature)			DATE	TIME	RECEIV	ED BY:	(Signatu	re)			7		<u> </u>	TIME	
RELINQUISHED BY: (Signature)		***************************************	DATE	TIME	RECEIV	ED BY:	(Signatu	re)					DATE	TIME	
SEND INVOICE TO:				L								·			-
					WHITE	COPY:	Accom	panies Sa	mples				4) 1.		
					YELLO	W COP	Y: Samo	ler					i	!	

ATTACHMENT 9 LIMITATIONS

The purpose of an environmental assessment is to reasonably evaluate the potential for or actual impact of past practices on a given site area. In performing an environmental assessment, it is understood that a balance must be struck between a reasonable inquiry into the environmental issues and an exhaustive analysis of each conceivable issue of potential concern. The following paragraphs discuss the assumptions and parameters under which such an opinion is rendered.

No investigation is thorough enough to exclude the presence of hazardous materials at a given site. If hazardous conditions have not been identified during the assessment, such a finding should not therefore be construed as a guarantee of the absence of such materials on the site, but rather as the result of the services performed within the scope, limitations, and cost of the work performed.

Environmental conditions may exist at the site that cannot be identified by visual observation. Where subsurface work was performed, our professional opinions are based in part on interpretation of data from discrete sampling locations that may not represent actual conditions at unsampled locations.

Except where there is express concern of our client, or where specific environmental contaminants have been previously reported by others, naturally occurring toxic substances, potential environmental contaminants inside buildings, or contaminant concentrations that are not of current environmental concern may not be reflected in this document.

The services described in this report were performed consistent with generally accepted professional consulting principles and practices. No other warranty, express or implied, is made. These services were performed consistent with our agreement with our client. This report is solely for the use and information of our client unless otherwise noted. Any reliance on this report by a third party is at such party's sole risk.

Opinions and recommendations contained in this report apply to conditions existing when services were performed and are intended only for the client, purposes, locations, time frames, and project parameters indicated. We are not responsible for the impacts of any changes in environmental standards, practices, or regulations subsequent to performance of services. We do not warrant the accuracy of information supplied by others, nor the use of segregated portions of this report.

PJC\C340801C.DOC